

DCC 19 Heat on:

FRIDAY, OCTOBER 13th, 2017.

Usually when heat is turned on, some heating components, (the expansion joint) may leak. Residents are reminded to place a container/towels under their heating component and check regularly throughout the heating season for any signs of water leak.

Your heating component is mostly found in the first bedroom, at the right or left of the Radiator. The "01" units is mostly found in the master bedroom.

Water leak must be reported immediately to the Superintendent on duty:

Gino @ 905-424-1566 - Monday to Friday Sylvan @ 905-424-5173 - Weekends and holidays

As done in the past, resident can pick up 1 aluminum dish (1 per unit) from the office or from the on duty superintendent.

It is very important to remove air conditioners from windows to prevent heat loss and frosted pipes.

PLEASE NOTE DCC 19, WILL NOT ACCEPT RESPONSIBILITY FOR PROPERTY DAMAGE RESULTING FROM RESIDENTS NEGLIGENCE.

Thank you.

Sandra
Property Administrator, DCC 19