

**NOTICE FOR ALL RESIDENTS AT THE BAYSHORE**  
**HEATING SYSTEM RE-SCHEDULE**



**PLEASE BE ADVISED THE BOILERS FOR THE HEATING SYSTEM**  
**HAS BEEN RE-SCHEDULED TO FUNCTION ON WEDNESDAY,**  
**OCTOBER 23<sup>RD</sup>, 2019.**

Usually when heat is turned on, some heating components, (the expansion joint) may leak. **Residents are reminded to place a container/towels under their heating component and check regularly throughout the heating season for any signs of a water leak.**

Your heating component is mostly found in the first bedroom, at the right or left of the Radiator. The "01" units is mostly found in the master bedroom.

**Water leaks must be reported immediately to the Superintendent:**

**Sylvan @ 905-424-5173**

As done in the past, residents can pick up 1 aluminum dish (1 per unit) from the office or from the superintendent.

**It is very important to remove air conditioners from windows to prevent heat loss and frosted pipes.**

**PLEASE NOTE DCC 19, WILL NOT ACCEPT RESPONSIBILITY FOR PROPERTY DAMAGE RESULTING FROM RESIDENTS NEGLIGENCE.**

Thank you,  
Vanessa Lewis  
Property Manager  
[www.thebayshore.net](http://www.thebayshore.net)